# FST

EIT Quick Test Intl
Special Features

Calibration Certificates:

We have included a way to have your calibration certificates easily available in case you are questioned while on a test site.


Click on the "Help" tab , then "About"

Then click on the "Calibration Certificates" button

This will bring up your calibration certificates, and "Calibration Requirements and Service" along with the TEC Equipment Service Form for recalibration of your equipment..

When you have your gauge or fan recalibrated, scan the certificates as a .pdf and place them in the "calibration certificates" folder which is located in the "references" folder which is located on your hard drive where you installed the program.

If you have questions about the NFPA calibration requirements please review the "Calibration Requirements and Service" page.

If your gauge or fan needs calibration fill out the "TEC Equipment Service Form" and send them directly to The Energy Conservatory in Minneapolis.

Fire Safety Technology
P.O. Box 1063
Severna Park, MD 21146 U.S.A.
Phone 800-685-8303, 410-647-8303
FAX 410-647-7066
e-mail: mail@firesafetytech.com
www.firesafetytech.com